

Clock Spring Repairs 42-inch Suction Line at Storage Terminal

Clock Spring Repairs 42-inch Suction Line at Storage Terminal

Africa

Pipe Details

- 42-inch (1,067 mm) suction line at a storage terminal
- Extensive pitting and corrosion

Summary

- A 42-inch (1,067-mm) suction line at a storage terminal had sustained extensive pitting and corrosion – in some places, resulting in 80% metal loss – and needed immediate repair.
- Extensive corrosion and pitting required installers to prepare the pipe for repairs by hand.
- Clock Spring trained technicians installed the Clock Spring repair sleeves using a spool feeder
- Line remained in service during repair



Starter pad application.



Filler application.



Pipe surface cleaned with solvent wipe.



Additional area for filler application.

A 42-inch (1,067 mm) suction line at a storage terminal had sustained extensive pitting and corrosion – in some places, resulting in 80% metal loss – and needed immediate repair. The corrosion occurred in areas in which the pipe coating had not prevented moisture ingress. Where moisture was entrapped, there was considerable galvanic corrosion.

Unfortunately, extensive corrosion was not the only concern. When the pipe was excavated, large areas were coated with “coal tar,” which had to be removed carefully by hand, followed by the removal of an additional layer of corrosion underneath. This painstaking process was necessary to avoid further damage to the pipe.

Once the coating and corrosion scale were removed manually, a nondestructive test (NDT) inspection was carried out to determine an accurate measurement of the remaining wall thicknesses. The NDT inspection pinpointed the worst areas of the pipe as well as areas where power tools could be used to prepare the pipe for the Clock Spring repair without further penetration/perforation of the remaining wall thickness. The Clock Spring trained team used pneumatic descaling guns and 3-inch by 7-inch (76-mm by 178-mm) grinding machines fitted with wire wheels to prepare the pipe surface to a NACE 3 standard. Electrical supply limitations meant only three machines could operate at a time.



Additional area for filler application.



Installer cutting the coil to bridge the weld using diamond cutting disc.



Bridged girth weld



Gap filled in with filler solution. Clock Spring wrap will "bridge" over the joint.

Pitting and general corrosion were extensive, with most of the severely corroded pipe previously buried in the concrete bund wall. The surface extent of the corrosion and the considerable length of the pipeline that needed to be repaired led to a decision to use sand-blasting for the remaining pipe section length.

The extent of corrosion had affected the ovality of the pipe, and filler was needed to bring the surface of the pipe back to its original outer diameter. The filler was held within a 42-inch (1,067 mm) mold and secured with tensioning straps to ensure even distribution around the pipe and into the corrosion pits. Surplus filler is extruded from the mold, leaving a uniform surface for the Clock Spring repair. This procedure was carried out on all longitudinal and spiral weld seams to avoid gaps and tenting underneath the Clock Spring coil. The severe circumferential extent of the corrosion made it necessary to apply filler to almost three quarters of the overall pipe circumference in some areas.

After the filler compound cured, the installation team removed the tensioning straps and mold and cleaned the pipe surface with solvent to remove grease or other forms of contamination deposited during the blasting process.

With the pipe properly cleaned, the team applied the Clock Spring starter pad and began installation of the Clock Spring units using a spool feeder because of the pipe diameter and limited clearance underneath the line. Once the coil was wound around the pipe and adhesive was applied to the complete surface area of the coil, installers slid the sleeve into place over the filler and onto the starter pad. The coils were installed side by side to accommodate the complete repair length and external extent of the corrosion. Each coil was tightened using the cinch bar to extrude excess filler and adhesive and ensure all the voids were filled completely.

During the 2 hours while the units cured, installers removed the excess filler and adhesive. The final step of the installation procedure was to apply a suitable corrosion coating over the complete length of the reinforcement to protect the repair.



Cured filler compound (30 minutes) and is ready for Clock Spring coil installation.



Filler is held with a 42" mold to ensure filler is equally distributed around the pipe and "fills" the corrosion pits.



Sand-blasting crew on the pipe section.



Sand-blasting of the remaining pipe section length.

There are nearly 3,000 trained Clock Spring installers around the world who are qualified to provide repairs with Clock Spring products. Clock Spring regularly offers training classes for installers and can custom design training for individual company needs.



Extensive pitting and general corrosion.



Extensive pitting and general corrosion.



Extensive pitting and general corrosion.



Section of the pipe cleaned to a NACE 3 standard.



Two pneumatic descaling guns used in tandem with 3"x7" grinding machines fitted with wire wheels.



NDT inspection completed and prep surface for Clock Spring repair.



NDT inspection process taking place.



Gradually remove the scale and coating for NDT inspection.



Cleaned pipe surface for NDT inspection.



Corrosion scale manually removed using hand tools.



Second layer of corrosion scale needed to be removed.



Corrosion area




Corrosion and condition of the "coal tar" coating on the pipe immediately after excavation.



The coil tightened using the cinch bar to extrude excess filler and adhesive.



Installation of Clock Spring using the spool feed method.



Adhesive exiting the side of Clock Spring coil from tightening.